| Work Orde Wednesday, Apri | | | | | | | | | | | Page 1 | | |
|--|-------------|---------------------------|------------------------|-------------------------|---------|-------|----------|---------------|---------------|--------|--------|--|--|
| Item ID: D3544-041 Revision ID: Item Name: Clamp Start Date: 4/27/2011 Start Qty: 30.00 Required Date: 4/29/2011 Req'd Qty: 30.00 Reference: | | | Accept | Cust Item ID: Customer: | | | Setup | Start Stop | | | | | |
| Approvals: | Process Pla | n: | Date: | Tooling: | | Date: | · | Run | Start Stop | | | | |
| Sequence ID/ | QC: | Operation | Date: | SPC (Y/N): Set Up/ | Tool ID | Date: | Plan Acc | ept Rej | ject | Reject | Insp. | | |
| Work Center ID Draw Nbr | | Description ision Nbr | | Run Hours | | | Code Qty | Qty | y : | Number | Stamp | | |
| D3544 | Rev | | | | | | (2) | \(\) | | | | | |
| Small Fab | | Small Fab Memo | per Dwg D3544 | 0.00 | m-k | 11/04 | 1/27 | | | | | | |
| QC Quality Control | | QC5- Inspect part comple | eteness to step on W/O | 0.00 | cab) | | (cm | ts 30) | | | | | |
| 120 | | Identify as per dwg & Sto | ock Location: | 0.00 | | | | 14/27 | | 0 | _ | | |

| | | | , | | | | | | | | | | |
|--|---|------------|--------------------------|---------------------|----------------------|--------------------------|--------|--|---|------------|-----------|------------------|----------------|
| Work Order ID 68994 Wednesday, April 27, 2011 6:33:57 AM | | | | | | Management and a second | | , and a second s | A DE AND AND A DESCRIPTION OF THE PROPERTY OF | Page | | | |
| Revis | tem ID: D3544-041 Revision ID: tem Name: Clamp tart Date: 4/27/2011 Start Qty: 30.00 Required Date: 4/29/2011 Req'd Qty: 30.00 | | | | Accept | | | Setup | Start | | | | |
| Start Requ | | | | | | Cust Item I Customer: | | | Эсор | | | | |
| | rence: | Dungang Pl | | Doto | Toolings | n | ate: | | | Run | Star | t | |
| Appr | Approvals: Process Plan:QC: | | Date: | Tooling: SPC (Y/N): | Date: | | | | | Stop | | | |
| | ence ID/ k Center | ID | Operation Description | | Set Up/ Run Hours | Tool ID | Tool # | Plan Code | Accept Qty | Rej Qty | ject y | Reject Number | Insp. Stamp |
| 130 | | | QC21- Final Inspection - | Work Order Release | 0.00 | | | | | | | n ly | 274 |
| QC | | | Memo | | 0.00 | | | | | | | | 7 |

Quality Control

M412797 MF 11-04-27

Page 2

Work Order ID: 68994

Parent Item:

D3544-041

Parent Item Name: Clamp



Start Date: 4/27/2011

Required Date: 4/29/2011

Start Qty: 30.00

Required Qty: 30.00


Comments:

IPP Rev:A New Issue 06-08-29 JLM

| Component Item ID/ Item Name | Replacement Item ID | Mfg/ Purch | Bin Item | Primary Location | Last Location | Route Seq ID | Unit of Measure | Qty on Hand | Qty per Kit | Total Qty | Qty Issued | Date Issued | Status |
|---------------------------------|------------------------|---------------|-------------|--------------------------|------------------------|-----------------|---------------------------------|----------------|----------------|-----------------|---------------|----------------|--------|
| D2182 | | Manufactured | No | | | 100 | f | 580.0000 | 0.585 | 18.47368 M-L | | 1041 | /27 |
| | • | | | Location | | Loc | Qty | Loc Code | | | | | |
| D2947 | | Manufratural | No | | 21864 26009 3999 | 100 | 580 230 256 94 Each | 100.0000 | | | 736 | 8 | |
| Clamp | | Manufactured | 140 | | | 100 | Cach | 100.0000 | | 30 M-J | 14 | 104 | 127 |
| | | | | <u>Location</u> ST457 | 63320 | Loc | <u>Oty</u> 100 100 | Loc Code | - . | 30× | | | |



DESIGN DRAWN BY DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA CHECKED DRAWING NO. REV. A D3544 SHEET 1 OF 1 DATE TITLE SCALE 06.08.11 **CLAMP** DATE DESCRIPTION REV A 06.08.11 **NEW ISSUE**



D3544-041 CLAMP

Mo 68944

RELEASED